

Inventory Data:										
Structure Name	#49 Joe Trudeau Bridge									
Main Hwy/Road#		On <input checked="" type="checkbox"/>	Under	Crossing Type	Navig. Water Rail	Water Road	Non-Navig. Water Ped.	Other		
Hwy/Road Name	Courneya Road									
Structure Location	0.5km west of Allore Road									
Latitude	44.483208°N			Longitude	77.227504°W					
Owner(s)	Municipality of Tweed			Heritage Designation:	Not Cons. <input checked="" type="checkbox"/>	Cons./not App. Desig./not List	List/not Desig. Desig. & List			
MTO Region	Eastern			Road Class:	Freeway	Arterial	Collector	Local <input checked="" type="checkbox"/>		
MTO District	Kingston			Posted Speed	80 km/h		No. of Lanes	1		
Old County				AADT			% Trucks			
Geographic Twp.				Inspection Route Sequence						
Structure Type	Half-Through Truss			Interchange Number						
Total Deck Length	19.5m		(m)	Interchange Structure Number						
Overall Str. Width	5.5m		(m)	Min. Vertical Clearance	2.3		(m)			
Total Deck Area	107		(sq.m)	Special Routes	Transit	Truck	School	Bicycle		
Roadway Width	5		(m)	Detour Length Around Bridge	8		(km)			
Skew Angle	0		(Deg.)	Direction of Structure	East-West					
No. of Spans	1			Fill on Structure	0		(m)			
Span Lengths	18.5								(m)	

Historical Data:			
Year Built		Last Evaluation	
Last Biennial Inspection	2020-10-01	Current Load Limit	10 (tonnes)
Last Bridge Master Inspection		Load Limit By-Law#	2020-76
Last Condition Survey		By-Law Expiry Date	
Last Underwater Inspection			

Rehab History: (Date/description)

1. 2008 – Replacement of interior steel stringers with wood and steel stringers

Scheduled Improvements:	
Regional Priority Number	<input style="width: 150px; height: 20px;" type="text"/>
Programmed Work Year	<input style="width: 150px; height: 20px;" type="text"/>
Nature of Program Work:	

Appraisal Indices:	Comments
Fatigue	
Seismic	
Scour	
Flood	
Geometrics	
Barrier	
Curb	
Load Capacity	

Field Inspection Information:	
Date of Inspection:	June 2, 2022
Inspector:	Abdul Rahman Stott
Others in Party:	Cody Chambers
Equipment Used:	Camera and hand tools
Weather:	Overcast
Temperature:	16°C

Additional Investigations Required:	Priority		
	None	Normal	Urgent
Detailed Deck Condition Survey:	X		
Non-destructive Delamination Survey of Asphalt-Covered Deck:	X		
Substructure Condition Survey:	X		
Detailed Coating Condition Survey:	X		
Underwater Investigation:	X		
Fatigue Investigation:	X		
Seismic Investigation:	X		
Structure Evaluation:		X	
Monitoring of Deformations, Settlements and Movements:	X		

The structure is generally in fair condition.

Recommended actions:

- Replace structure to improve level-of-service (1-5 yrs.)
- Repair localized deck failure (NOW)
- Remove overgrowth at abutments as part of structure maintenance

BCI (2020): 49.75

BCI (2022): 47.70

Next Detailed Visual Inspection:	2024
----------------------------------	------

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 00 None | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 01 Load carrying capacity | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 02 Excessive deformations (deflections & rotations) | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 03 Continuing settlement | 09 Rough riding surface | 15 Unstable embankments |
| 04 Continuing movements | 10 Surface ponding | 16 Other |
| 05 Seized bearings | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|-------------------------------|
| 01 Lift and Swing Bridge Maintenance | 07 Repair of Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges – Maintenance | 16 Bridge Deck Drainage |
| 05 Bridge Deck Joint Repair | 11 Animal/Pest Control | 17 Other |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | |

Element Data

Element Group:		Abutments		Length		N/A		
Element Name:		Abutment Walls		Width		6m		
Location:		Either end of structure		Height		2.5m		
Material:		Cast-in-place Concrete		Count		2		
Element Type:		Conventional Closed		Total Quantity:		30m ²		
Environment:		Moderate		Limited Inspection		<input type="checkbox"/>		
Protection System:		None				Perform. Deficiencies		Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	Maint. Needs	
Data:	m ²	0	10	8	12			
Comments: Medium to vertical wide crack, horizontal cracks with efflorescence, and severe scaling and erosion at corners and waterline of east abutment. West abutment recently refaced and exhibits light AAR and narrow cracks. Wood diaphragm blocking transfers load to east abutment.								
Recommended Work: None <input checked="" type="checkbox"/> 6-10 years <input type="checkbox"/> 1-5 years <input type="checkbox"/> <1 year <input type="checkbox"/> Urgent <input type="checkbox"/>								

Element Group:		Abutments		Length				
Element Name:		Bearings		Width				
Location:		on abutment walls		Height				
Material:		Steel		Count		4		
Element Type:		Plate		Total Quantity:		4		
Environment:		Moderate		Limited Inspection		<input type="checkbox"/>		
Protection System:		None				Perform. Deficiencies		Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	Maint. Needs	
Data:	Each	0	0	3	1			
Comments: Medium to severe corrosion. Loss of concrete abutment at southeast limiting bearing area. Overgrown with vegetation at southeast.								
Recommended Work: Remove overgrown vegetation as part of structure maintenance None <input type="checkbox"/> 6-10 years <input type="checkbox"/> 1-5 years <input type="checkbox"/> <1 year <input type="checkbox"/> Urgent <input type="checkbox"/>								

Element Group:		Abutments		Length		6m		
Element Name:		Wingwalls		Width				
Location:		Four quadrants		Height		3.2m		
Material:		Cast-in-place Concrete		Count		4		
Element Type:				Total Quantity:		76.8m ²		
Environment:		Moderate		Limited Inspection		<input type="checkbox"/>		
Protection System:		None				Perform. Deficiencies		Maint. Needs
Condition	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	Maint. Needs	
Data:	m ²	0	35	26.4	15.4			
Comments: Medium to severe scaling and medium to wide horizontal cracks on eastern wingwalls. Large spall at southeast wingwall bearing area. Light honeycombing at southwest wingwall.								
Recommended Work: None <input checked="" type="checkbox"/> 6-10 years <input type="checkbox"/> 1-5 years <input type="checkbox"/> <1 year <input type="checkbox"/> Urgent <input type="checkbox"/>								

Element Group:	Decks	Length	19.5m				
Element Name:	Deck Top - Thin Slab	Width	5.5m				
Location:	Spanning between abutments	Height					
Material:	Wood	Count	1				
Element Type:	Laminated Wood Decking	Total Quantity:	107m ²				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	Maint. Needs
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*		
		0	47	55	5	00	
Comments: Decking exhibits splits. Extensive accumulation of gravel debris. Running boards are in good condition with some splitting at the edges.							
Recommended Work: None <input checked="" type="checkbox"/> 6-10 years <input type="checkbox"/> 1-5 years <input type="checkbox"/> <1 year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Decks	Length	19.5m				
Element Name:	Soffit – Thin Slab	Width	5.5m				
Location:	Underside of deck	Height					
Material:	Wood	Count	1				
Element Type:		Total Quantity:	107m ²				
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	Maint. Needs
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*		
		0	94	12	1	00	
Splitting and checking. Localized deck failure at midspan.							
Recommended Work: Locally remove and replace split deck board None <input type="checkbox"/> 6-10 years <input type="checkbox"/> 1-5 years <input type="checkbox"/> <1 year <input type="checkbox"/> Urgent <input checked="" type="checkbox"/>							

Element Group:	Joints	Length	5.5m				
Element Name:	Seals/Sealants	Width	N/A				
Location:	Either end of deck	Height	N/A				
Material:	Other	Count	2				
Element Type:	Strip Seal	Total Quantity:	2				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	Maint. Needs
Condition Data:	Units Each	Exc.	Good	Fair	Poor*		
		0	0	0	2	00	
Debris accumulation at joint area at both ends of the deck. No seal is visible at either end.							
Recommended Work: None <input checked="" type="checkbox"/> 6-10 years <input type="checkbox"/> 1-5 years <input type="checkbox"/> <1 year <input type="checkbox"/> Urgent <input type="checkbox"/>							

Element Group:	Beams/MLEs	Length	19.5m						
Element Name:	Stringers	Width	0.125m						
Location:	Spanning longitudinally under deck	Height	0.5m						
Material:	Steel	Count	24						
Element Type:	I-Type	Total Quantity:	24						
Environment:	Benign	Limited Inspection	<input type="checkbox"/>						
Protection System:	None						Perform. Deficiencies	Maint. Needs	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each	0	0	20	4	00			
Comments: Light to medium corrosion, localized deformation, and severe section loss at west end. Ends reinforced with timber sections.									
Recommended Work: None <input checked="" type="checkbox"/> 6-10 years <input type="checkbox"/> 1-5 years <input type="checkbox"/> <1 year <input type="checkbox"/> Urgent <input type="checkbox"/>									

Element Group:	Trusses/Arches	Length	15.1m						
Element Name:	Top Chords	Width	0.1m						
Location:	Either edge of deck	Height	0.15m						
Material:	Steel	Count	2						
Element Type:	Chanel	Total Quantity:	21.1						
Environment:	Benign	Limited Inspection	<input type="checkbox"/>						
Protection System:	None						Perform. Deficiencies	Maint. Needs	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²	0	19	2.1	0	00			
Comments: Light to medium corrosion and coating loss									
Recommended Work: None <input checked="" type="checkbox"/> 6-10 years <input type="checkbox"/> 1-5 years <input type="checkbox"/> <1 year <input type="checkbox"/> Urgent <input type="checkbox"/>									

Element Group:	Trusses/Arches	Length	19.5m						
Element Name:	Bottom Chords	Width	0.1m						
Location:	Either edge of deck	Height	0.15m						
Material:	Steel	Count	2						
Element Type:	Chanel	Total Quantity:	27.3						
Environment:	Severe	Limited Inspection	<input type="checkbox"/>						
Protection System:	None						Perform. Deficiencies	Maint. Needs	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²	0	17.8	9	0.5	00			
Comments: Light to medium corrosion, worsening at connections. Deformation at southeast.									
Recommended Work: None <input checked="" type="checkbox"/> 6-10 years <input type="checkbox"/> 1-5 years <input type="checkbox"/> <1 year <input type="checkbox"/> Urgent <input type="checkbox"/>									

BRIDGE PHOTOGRAPHS

Owner: Municipality Of Tweed
Hwy/Road Name: Courneya Road

Structure Name: Joe Trudeau Bridge
Location: 0.50 km west of Allore Road



Photo 1: Deck Top Looking East



Photo 2: South Tuss and Barrier with Missing Tube Railing

BRIDGE PHOTOGRAPHS

Owner: Municipality Of Tweed
Hwy/Road Name: Courneya Road

Structure Name: Joe Trudeau Bridge
Location: 0.50 km west of Allore Road




Photo 3: South Elevation



Photo 4: East Abutment Wall

BRIDGE PHOTOGRAPHS

Owner: Municipality Of Tweed
Hwy/Road Name: Courneya Road

Structure Name: Joe Trudeau Bridge
Location: 0.50 km west of Allore Road



Photo 5: Interior Soffit, Stringers, and Floor Beams Looking West



Photo 6: Loss of Truss Bearing at Southeast Abutment Wall

BRIDGE PHOTOGRAPHS

Owner: Municipality Of Tweed
Hwy/Road Name: Courneya Road

Structure Name: Joe Trudeau Bridge
Location: 0.50 km west of Allore Road



Photo 7: West Abutment Wall




Photo 8: Bulging of Southwest Retaining Wall

BRIDGE PHOTOGRAPHS

Owner: Municipality Of Tweed
Hwy/Road Name: Courneya Road

Structure Name: Joe Trudeau Bridge
Location: 0.50 km west of Allore Road




Photo 9: Localized Deck Failure



Photo 10: Typical Bottom Chord Floor Beam Connection

Joe Trudeau Bridge Location




2/8/2023, 4:15:55 PM

Civic Addresses

 Property Information

1:4,514




Hastings County, Province of Ontario, Ontario MNR, Esri Canada, Esri, HERE, Garmin, INCREMENT P, USGS, EPA, USDA, AAFC, NRCan

Hastings County GIS


Information purposes only and may not be suitable for legal, engineering, or surveying purposes. The County of Hastings disclaims all responsibility for errors, omissions or inaccuracies in this publication. Data supplied under License with OGDE & MPAC.

Joe Trudeau Bridge Detour



8/29/2023, 2:27:20 PM


- Trans Canada Trail
- Property Information



Hastings County, Province of Ontario, Ontario MNR, Esri Canada, Esri, HERE, Garmin, INCREMENT P, USGS, METI/NASA, EPA, USDA, AAFIC.

Hastings County GIS

Information purposes only and may not be suitable for legal, engineering, or surveying purposes. The County of Hastings disclaims all responsibility for errors, omissions or inaccuracies in this publication. Data supplied under License with OGDE & MPAC.



Hand-drawn map showing a red-outlined polygonal area on a grid. The area is roughly rectangular with a small protrusion on the right side. The map includes a grid of dashed lines and a larger, fainter grid in the background.

Hand-drawn map showing a red-outlined polygonal area on a grid. The area is roughly rectangular with a small protrusion on the right side. The map includes a grid of dashed lines and a larger, fainter grid in the background.